

qf
w

LOGNOTE -- Chief, Operations Group, 17 November 1983

STAT

2. [] I asked [] today to see whether anything can be done through GSA to improve the airconditioning layout in the ComCtr. The two large vents there are directing too much cold air to the staff and not enough to the equipment, causing an uncomfortable working environment and a potential health risk. One person is out now with a case of pneumonia, which may be partially, if not totally, attributable to the stiff draft blowing down from the vents. [] meanwhile would like to see more cool air get to the MIDAS equipment.

STAT

[] took a look at the situation with C/ComCtr and asked him to prepare a formal request for action which [] can use to prepare a work order for GSA. We all know it will take time for GSA to act, but the sooner we start the better.

STAT

STAT

(cc: C/E&PS, C/Admin Staff, C/DRD, C/ComCtr, C/Logs/AS)